

Film scanner panel does not work after upgrading

Scope:

OmniPro Accept version 6.5A

Indication:

After upgrading OmniPro Accept to version 6.5A from 6.4A or earlier version, several error messages concerning the film panel appears

Cause:

When upgrading the setup program must be run twice. The first run replaces the existing files with newer versions, the second run adds new file e.g. the new film scanner panel. This is indicated by a message at the end of the first run.

Solution:

Run the setup program a second time. Select Modify.